
Advanced Hall Lantern
Intermediate Landing: 30
Volt Application w/o
Remote Station

Spare Parts Leaflet 34-6646EB

October 28, 2009 / Page 1 of 4



History

Leaflet Description

This leaflet was separated from SPL C-3029 in July 1997.

Leaflet Revisions

Date Revised	Subject Matter Expert	Reason for Revision
July 1997		Separated from SPL C-3029
October 28, 2009	Joseph Zych	Added 354AG6 and rearranged page layout.

Related Drawings

Drawing No.	Title	Drawing No.	Title
6646EB	Assembly and Arrangement, Hall Lantern (intermediate)		

Related Documents

Document ID	Title
SPL C-3029	Advanced Hall Position Indicator (Flat Faceplate Design) 6646EG

Subject Matter Expert

Name	Department
Joseph Zych	OSC Service Engineering

About Spare Parts Leaflets...

This document lists the lowest replaceable units (LRUs) for the standard version of the product. The LRUs are chosen by a team of Otis associates representing engineering and manufacturing.


While goal of this document is to make parts identification as easy as possible, the document cannot be all-inclusive. Elevator and escalator contracts classified as "special" or "custom" are not addressed here. For such contracts, please refer to specified information, the contract folder, TIPs, Field Education Articles, Construction Letters, etc. for further information.

If you have any suggestions about this document, please contact the subject matter expert listed on this page.

Page 2	October 28, 20	009
rage Z	OCTOBEL 20, 20	<i>,</i> $_{0}$

Hall Lantern Assembly

34-6646EB




^{**} General Location. Part Not Illustrated.

(Continued on next page)

^{***} A8200BE2 is a functional substitute, and the gong sound may differ. If objectionable, contact Customer Service for repair of 8200BE2.

34-6646EB

Hall Lantern Assembly



^{*} Recommended Spare Part

Dono 4	0-4-h 29 2000	
Page 4	October 28, 2009	