
i-MOTION® II and Linkage Assemblies (GEN2)

Spare Parts Leaflet 23-AAA24470W

November 20, 2019 / Page 1 of 7





This document does not contain any technical data subject to EAR or ITAR

SERVICE ENGINEERING
Otis Elevator Company
Bloomfield, Connecticut USA

Unpublished Work—© Otis Elevator Co.; 2019

History

Leaflet Description

This leaflet provides spare parts information for i-MOTION II door operator linkage assemblies for center-opening, single-slide, and two-speed GEN2 door systems.

Leaflet Revisions

Date Revised	Subject Matter Expert	Reason for Revision
December 4, 2013	Brian Regan	New SPL
November 20, 2019	Peter Kelley	Revised history page

Related Drawings

Drawing No.	Title	Drawing No.	Title
AAA24470W	Arrangement i-MOTION II and Linkage Assembly for Center- Opening Doors (GEN2)	AAA24450Z	Arrangement i-MOTION II and Linkage Assembly for Single-Slide Doors (GEN2)
AAA24460L	Arrangement i-MOTION II and Linkage Assembly for Two- Speed Doors (GEN2)	AAA24350BH	Door Operator i-MOTION II C/O, S/S, 2/S

Related Documents

Document ID	Title	
SPL 23-AAA24350BH	Harmonic Drive i-MOTION II Door Operator Engine Unit	
SPL 24-AAA24390J	Door Coupler, NG Door System	
SPL 19-AAA24600A	Car Door hanger and Track, NG Door Systems: S/S, C/O, 2/S	

Subject Matter Expert

Name	Department
Peter Kelley	OSC Service Engineering


About Spare Parts Leaflets...

This document lists the lowest replaceable units (LRUs) for the standard version of the product. The LRUs are chosen by a team of Otis associates representing engineering and manufacturing.

While goal of this document is to make parts identification as easy as possible, the document cannot be all-inclusive. Elevator and escalator contracts classified as "special" or "custom" are not addressed here. For such contracts, please refer to specified information, the contract folder, TIPs, Field Education Articles, Construction Letters, etc. for further information.

If you have any suggestions about this document, please contact the subject matter expert listed on this page.

Page 2	November 20, 2019




NOTE: For more detailed information on component parts of the engine assembly,

SPL 23-AAA24350BH.

23-AAA24470W


Linkage Components C/O Doors



NOTE: References 6 and 7 are not included w/ref. 3. Order 4 of each per each ref. 3 ordered.

Linkage Components C/O Doors


23-AAA24470W




	AAA24470W	
REF. No.	PART No.	DESCRIPTION
1	395F3	Arm, Transmission
2	AAA299ANY4	Bar, Drive Arm Mounting (two per assembly)
3	AAA124HG1	Bolt, Shoulder, Metric M8 x 20
4	AAA316GLW2	Bracket, Gate Switch
5	462HA144	Spacer, Aluminum, = 0.42 in. (one per assembly)
6	462HA145	Spacer, Steel, = 0.34 in. (two per assembly)
7	AAA25590X1	Switch, Gate
8	128AF18	Washer (shim), Ø 0.75 in., 0.016 in. Thick (quantity may vary)
9	ISO7089M10-140HV-Z	Washer, M10, 2 mm Thick
10	ISO7093M8-140HV-Z	Washer, M8

23-AAA24470W

Linkage Components S/S and 2/S



NOTE: References 6 and 7 are not included w/ref. 3. Order 4 of each per each ref. 3 ordered.



(quantity may vary)

Washer, M8

Washer, M10, 2 mm Thick

ISO7089M10-140HV-Z

ISO7093M8-140HV-Z

9 10