
In-Car Lantern Assembly

Spare Parts Leaflet

31-AAA6463AB

March 1, 2000 / Page 1 of 3



History

31-AAA6463AB

In-Car Lantern Assembly

First Published: March 1, 2000

REVISED DATE	RESPONSIBLE ENGINEER	PRIMARY REASON FOR REVISION
March 1, 2000	Stephen Karvazy	New leaflet

Leaflet Description

This leaflet provides spare parts information for AAA6463AB1 & AAA6463AB2 in-car lantern arrangements.


RELATED LEAFLET NUMBERS	TITLES

DRAWING REFERENCES AAA6463AB

RELATED DOCUMENT NUMBERS	TITLES

This Spare Parts Leaflet (SPL) is prepared to assist you in determining the Lowest Replaceable Units (LRU) supported by the Otis Service Center for the standard version of the product titled on the preceding page. The parts are chosen by Otis associates from: Engineering, Field Engineering, Service Engineering, and Manufacturing. We attempt to make part identification as easy as possible. The SPL, however, cannot be all inclusive. Elevator and escalator contracts classified as either "special" or "custom" are not addressed. Alternative sources of information such as: the Contract Folder, Technical Information Publications, Field Education Articles, Construction Letters, etc. may give the information you are after. You live in the real world of maintaining your elevator and escalator contracts. On a daily basis, situations arise regarding parts identification and at times, for some reason, the part you need is not in the SPL. If you think a standard part not listed should be—let us know. We will respond.

Stephen Karvazy—OSC Service Engineering



March 1, 2000 Page 3