


**OCE521 Escalator
Handrail Drive**

Spare Parts Leaflet

55-ASA03C240

11/01/2006 / Page 1 of 4



OTIS

Safety First!

**Escalator Department
Otis Elevator Company
Changwon, Korea**

Leaflet Description

OCE521 Escalator Handrail Drive

Leaflet Revisions

Date Revised	Subject Matter Expert	Reason for Revision
November 1, 2006		Release

Related Drawings

Drawing No.	Title	Drawing No.	Title
ASA01A082	HR(U) Setting		

Related Documents

Document ID	Title
BOM	

Subject Matter Expert


Name	Department

About Spare Parts Leaflets...


This document lists the lowest replaceable units (LRUs) for the standard version of the product. The LRUs are chosen by a team of Otis associates representing engineering and manufacturing.

While goal of this document is to make parts identification as easy as possible, the document cannot be all-inclusive. Elevator and escalator contracts classified as "special" or "custom" are not addressed here. For such contracts, please refer to specified information, the contract folder, TIPs, Field Education Articles, Construction Letters, etc. for further information.

If you have any suggestions about this document, please contact the subject matter expert listed on this page.



REF. No.	W/O VINTAGE	DESCRIPTION	TYPE
	PART No.		
1	ASA00B046D	HR Drive Assembly	600
	ASA00B046C	HR Drive Assembly	1000
2	ASA01B215A	Chain Roller Assembly	



W/O VINTAGE		
REF. No.	PART No.	DESCRIPTION
3	4L08510A	UCP Bearing
4	ASA00B047B	Pulley
5	4L07981B	Key for HR
6	4L07993A	Cover
7	WSB3900O	Spring Washer (SW10)
8	BHD3944D	Bolt (M10x6)