


**OCE521 Escalator  
Inspection Device**

**Spare Parts Leaflet**

**32-ASA03C360**

**November 1, 2006 / Page 1 of 3**



**OTIS**

**Safety First!**

**ESCALATOR DEPARTMENT  
Otis Elevator Company  
Changwon, Korea**

**Leaflet Description**

OCE521 escalator inspection device.

**Leaflet Revisions**

<b>Date Revised</b>	<b>Subject Matter Expert</b>	<b>Reason for Revision</b>
Nov. 1, 2006	---	Release
---	---	---

**Related Drawings**

<b>Drawing No.</b>	<b>Title</b>	<b>Drawing No.</b>	<b>Title</b>
ASG00C226	Inspection Device	---	---
---	---	---	---

**Related Documents**

<b>Document ID</b>	<b>Title</b>
BOM	---
---	---

**Subject Matter Expert**

<b>Name</b>	<b>Department</b>
	Escalator Department

**About Spare Parts Leaflets...**


This document lists the lowest replaceable units (LRUs) for the standard version of the product. The LRUs are chosen by a team of Otis associates representing engineering and manufacturing.

While goal of this document is to make parts identification as easy as possible, the document cannot be all-inclusive. Elevator and escalator contracts classified as "special" or "custom" are not addressed here. For such contracts, please refer to specified information, the contract folder, TIPs, Field Education Articles, Construction Letters, etc. for further information.

If you have any suggestions about this document, please contact the subject matter expert listed on this page.

# OCE521 Escalator Inspection Device

**32-ASA03C360**



<b>W/O VINTAGE</b>		
<b>REF. No.</b>	<b>PART No.</b>	<b>DESCRIPTION</b>
1	ASG00C226C	Inspection Device